



A



B



图纸编码

Phase	3	Temperature Rise	Below 80K
Step Angle	1.2°	Insulation Withstand Voltage	500V A.C
Step Angle Error (No Load)	±0.06° or below	Insulation Resistance	Above 100 MΩ
Voltage	6.0 V	Insulation Class	B
Current	6.0 A	Operating Temperature Range	-20°C~+50°C
Resistance (Phase)	1.3 Ω±10%	Operating Humidity Range	20%RH~90%RH
Inductance (Phase)	17 mH±20%	Storage Temperature Range	-20°C~+70°C
Holding Torque	16 N.m	Storage Humidity Range	15%RH~95%RH
Rated Operating Status	Continuous	Lifetime (Hours)	Above 5000H
Rotor Inertia	14800g. cm²		

物料代码

453

版本 Rev

A1.0

变更内容

Revision Record


初次发放

签字The signature

日期 Date

2023.10.16

Note: The yellow-green line is the ground wire.




Excitation Sequence (3-Phase Excitation)

STEP	U	V	W
1	+	-	
2	-	+	
3	-	+	
4	-	+	-
5	+	-	
6	+	-	-

Initial Direction: Follow the excitation sequence in the table, observing the clockwise direction from the mounting surface.

CCW

CW



客户签字确认

标记

处数

更改文件号

签名 年 月 日

视图方式:



SMC4202

THREE-PHASE HYBRID STEPPING MOTOR



汉德保电机

WWW.HDMOTORS.COM

